

Download Manual 2015 Peugeot Rcz Owners Manual

here we go right got warning light on ignition oil level in correct. top up engine oil ,, but just had full service 2 months ago , any way put 2 litres of oil in stil getting warning. oil level does register on dip stick , but find not as easy to see as the ole dipsticks yeare and years ago. is it normal to get through this much oil any way hmmm thanks for any help one engine is running no warningRear spoiler doesn't rise at the pre set speed, and therefore doesn't return to closed either when speed drops, but it does respond to manual raising and closing at any speed by the button - any ideas where to look or just throw it back at the dealer as it is under warranty.31-12-2012: 'Gong' sound means that car battery is failing to hold sufficient charge and needs to be replaced. 24-9-2013: With the turbo petrol engine dealers recommend a change of engine oil after the first month or 1,000 miles to remove any tiny particles of swarf. 24-2-2015: Strange rubbing noise reported from flywheel area of 2013 Peugeot RCZ when driving away in 1st gear.The added power and a manual gearbox makes the Peugeot RCZ 200 a better driver's car this time around.